2 9 AUG 1974

MEMORANDUM FOR: Director of Logistics

THROUGH : Chief, Real Estate and Construction Division, OL

SUBJECT : Funds for New Air Handlers

REFERENCE: Computer Systems Planning Report dtd 6 Jun 74

by OJCS

1. A request for guidance in the funding of \$14,000 for the procurement and installation of new air handlers in room GC03, Office of Joint Computer Support (OJCS), is requested in paragraph 6.

- 2. The referent report identified a matrix of generalized space and utility requirements against various computer configuration assumptions through FY 1978. Specific equipment locations were not included in the report.
- 3. The specific equipment location for Milestone No. 1 of the report, the installation of the IBM 370/158-2, has now been identified. The unit is scheduled to be located in the southwest quadrant of GC03 served by perimeter air handler Nos. 6 and 7.
- 4. As previously identified, the underfloor congestion and multiple heating, ventilating, and air conditioning (HVAC) systems serving the GCO3 area present indeterminacy in HVAC designs. Within the constraints of this indeterminacy, analysis indicates that the existing air handlers may not have the capacity to meet the increased requirements of the 370/158-2 installation. In lieu of an indepth engineering study and relatively extensive modifications in the instrumentations and control of the HVAC systems, the only sure alternative to insure an acceptable environment will exist to support the installation in the area is to uprate air handler Nos. 6 and 7 from a 10-ton rating to a 20-ton rating. This will be an ad hoc action to insure adequate results for a specific installation in a specific area. This action will not contribute to the resolution of the overall HVAC problems in the OJCS Computer Center, nor will it necessarily be effective if the location of the 370/158-2 is altered to a new location in a different quadrant of the Center.

5.	OJCS	representat	ives	are	in	agreement	that	upra	ted	air	
		necessary, b					advis	es t	hat	ojcs	STAT

Approved For Release 2003/06/20 : CIA-RDP86-01019R000100240007-2

SUBJECT: Funds for New Air Handlers

FY 1975 funds are not available for this unanticipated requirement. The budgetary cost estimate for procurement and installation of the uprated units is \$14,000.

There is mutual agreement between Real Estate and Construction Division and OJCS that air handler Nos. 6 and 7 must be uprated to insure that an adequate environment will exist to support the new 370/158-2 computer. Neither OJCS nor OL has programmed funds in FY 1975 for this unanticipated requirement. OJCS has advised that funds are not available, and has requested OL to identify funds. Guidance is requested in the identification of approximately \$14,000 for the uprating of air handler Nos. 6 and 7.

Headquarters Engineering Branch, RECD/OL

STAT

		ROUTING	G AND	RECOR	SHEET		
SUBJECT	: (Optional)						
	Funds for New A	ir Handlei	rs.				
ROM:	C/HEB/RECD/OL			EXTENSION	NO.		
	2F42 Hqs.				DATE S		
O: (Official	ficer designation, room number, a	nd D	ATE	OFFICER'S	COMMENTS (Number each comment to show from whom to whom. Draw a line across column after each comment.		
		RECEIVED	FORWARDED		to whom. Draw of this decision column drief back comment.		
1.	C/RECD/OL 906 Ames	2	9 AUG 19	74	RE: Paragraph 6		
2.					Glenn:		
					Assume RECD would recommen		
3.					OL funds under policy that		
					planning and control of utili systems may be achieved only		
4.					if RECD is the sole source of		
					funding utility-related pro- jects. Possible we should		
5.					include a relatively large bu		
					undefined line item in FY 76 for unanticipated projects		
6.					like this and the GJ56 9K $_{ m ex}$ -		
				_	penditure. As I see it, ther		
7.					are four alternatives as follows listed in order of m		
					perception of desirability:		
8.					a. OL fund out of 1121		
					funds		
9.					b. OL reprogram and		
					fund		
0.					c. OL advise OJCS to		
				, <del>d</del> .,	reprogram through Di		
1.					d. Chance it and try to		
					get adequate air in		
2.					the location from spare capacity in		
				and our of the second	other air handlers.		
3.					To meet the Oct. installati		
					date, procurement must be		
4.					initiated in the immediate		
					coordinated with		
5.					of OJCS.		
				<b>_</b>	<i>Five</i> 1019R000100240€67V2		

Next 3 Page(s) In Document Exempt